

FDI	ENGINEERING CHANGE ORDER		ECO NO:
			Page 1 of 1
TITLE	DWG NO.	CURRENT REV	NEW REV
uEZGUI4.3	uEZGUI4.3	3.0	3.1

BACKGROUND:

- Change J8 and R57 from DNL to Load so the standard FDI product will be the same with one part assembly part number and one manufacturing configuration
- Add jumper wires to correct error in TP connectivity in Rev 3.0 artwork

DESCRIPTION OF CHANGE:

Documentation/Build;

- Change BOM , J8 from DNL to load
- Change BOM, R57 from DNL to load
- Increment revision of Docs to Rev 3.1 (SCH, and BOM)

Rework;

- Add wire from U13 pin 6 to R48.1 (pad nearest 'R48' legend, away from J6)
- Add wire from U13 pin 3 to R49.1 (pad nearest 'R49' legend, away from J6)

- Mark Assemblies as Rev 3.1 during manufacturing.

Reason for change: 1. Change J8 and R57 from DNL to Load to have one build configuration 2. Correct TP connectivity error		Disposition/Affectivity	
		Use as is	x
		Rework to ECO	x
		Scrap & Rebuild	
		Record Change Only	
Prepared by:	TE/MH	Date:	8/3/2011
Approved by:		Date:	
Approved by:		Date:	
Approved by:		Date:	