

FDI	ENGINEERING CHANGE ORDER		ECO NO: 09-004
			Page 1 of 1
TITLE	DWG NO.	CURRENT REV	NEW REV
LCDCARRIER	LCDCARRIER	2	2.1

BACKGROUND:

Update design to add support for LPC3250 Touch screen requirement. The LPC3250 requires XP be pulled down to ground via 100K resistor.

DESCRIPTION OF CHANGE:

1. On the bottom side of the board, add 100K pull down at J4 pin 1 to J4 pin 3



Reason for change: 1. LPC3250 requires 100K pull down on XP/XL		Disposition/Effectively	
		Use as is	
		Rework to ECO	X
		Scrap & Rebuild	
		Record Change Only	
Prepared by:	M.Hall	Date:	4/27/09
Approved by:		Date:	
Approved by:		Date:	
Approved by:		Date:	