

<b>FDI</b>	<b>ENGINEERING CHANGE ORDER</b>		<b>ECO NO: 12-122</b>
			<b>Page 1 of 1</b>
<b>TITLE</b>	<b>DWG NO.</b>	<b>CURRENT REV</b>	<b>NEW REV</b>
uEZGUI4.3	uEZGUI4.3	6.0	6.1

**BACKGROUND:**

- Implement new double face tape to keep LCD from separating from uEZGUI4.3 PCBA during wider temperature ranges of -40°F to 200°F

**DESCRIPTION OF CHANGE:**

1. Change double face tape used in assembly to ULINE P/N: S-10135, 3M4956 1/2x36 VHB Tape

Reason for change: 1. Change double face tape used in all uEZGUI assemblies to stay assembled during wider temperature ranges of -40°F to 200°F			<b>Disposition/Affectivity</b>	
			Use as is	
			Rework to ECO	x
			Scrap & Rebuild	
			Record Change Only	
Prepared by:	JS	Date:	10/30/2012	
Approved by:	MH	Date:	10/31/12	
Approved by:		Date:		
Approved by:		Date:		