

uEZGUI-1788-43WQR

Product Change Notification Form

PCN Number: 20130222-01	Rev: 6.2	Date: 02/22/2013
--------------------------------	-----------------	-------------------------

Summary of Change: uEZGUI-1788-43WQR-BA product revision release with the ISP connector removed

Reason for Change: For factory programming or field programming of uEZGUIs, FDI recommends customers use either the JTAG connector or the Tag-Connect JTAG pogo-pin connection. The ISP programming system is slower and does not have the capability to program external flash memory.

Detailed Description of Change: The ISP connector (J3) on the uEZGUI-1788-43WQR-BA is being changed to “Do-Not-Load” by default.

Products Affected:

Effected Product (Rev 6.1)	Recommended Replacement Product (Rev 6.1)
uEZGUI-1788-43WQR	uEZGUI-1788-43WQR
uEZGUI-1788-43WQR-BA	uEZGUI-1788-43WQR-BA
uEZGUI-1788-43WQR-BA-NT	uEZGUI-1788-43WQR-BA-NT

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers’ orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

02/22/13 PCN Date, the date this document was released for distribution to customers and distributors.

02/22/13 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.

Reference Documents: <http://www.teamfdi.com/support/touch-screen.php#uezgui-1788-43wqr>

1. uEZGUI-1788-43WQR Brochure.pdf
2. uEZGUI-1788-43WQR Quick Start Guide.pdf
3. uEZGUI-1788-43WQR Users Manual.pdf
4. uEZGUI-1788-43WQR_SCH_6.pdf
5. uEZGUI-1788-43WQR Rev 6 ECO
6. uEZGUI-1788-43WQR Rev 6.1 ECO
7. uEZGUI-1788-43WQR Rev 6.2 ECO



FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.