

uEZGUI-1788-43WQR

Product Change Notification Form

PCN Number: 20130329-01	Rev: 6.0	Date: 03/29/2013
--------------------------------	-----------------	-------------------------

Summary of Change: uEZGUI-1788-43WQR Family implementing new ESD protection features and battery protection diode

Reason for Change: FDI has added standard and optional ESD protection circuitry to the reset lines and other signals on the uEZGUI-1788-43WQR to improve the noise and ESD immunity. The new diode on the RTC battery circuit has less current leakage for longer battery life.

Detailed Description of Change:

The following parts were added to revision 6: C98, C97, R81, C99, D14, R79, and R80. Of these, the following are “Do Not Load” (DNL) by default: D14, and C99. D7 was changed to BAS40-05.

Products Affected:

Effected Product (Rev 5.0)	Recommended Replacement Product (Rev 6.0)
uEZGUI-1788-43WQR	uEZGUI-1788-43WQR
uEZGUI-1788-43WQR-BA	uEZGUI-1788-43WQR-BA

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers’ orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

03/29/2013 PCN Date, the date this document was released for distribution to customers and distributors.

03/29/2013 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.



Reference Documents: <http://www.teamfdi.com/support/touch-screen.php#uezgui-1788-43wqr>

1. uEZGUI-1788-43WQR Brochure.pdf
2. uEZGUI-1788-43WQR Quick Start Guide.pdf
3. uEZGUI-1788-43WQR Users Manual.pdf
4. uEZGUI-1788-43WQR_SCH_5.pdf
5. uEZGUI-1788-43WQR Rev 5 ECO
6. uEZGUI-1788-43WQR_SCH_6.pdf
7. uEZGUI-1788-43WQR Rev 6 ECO

FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.