

uEZGUI-1788-43WQR

Product Change Notification Form

PCN Number: 20150512-01	Rev: 7.3	Date: 05/12/2015
-------------------------	----------	------------------

Summary of Change: uEZGUI-1788-43WQR-BA change capacitors to increase the voltage rating.

Reason for Change: FDI is changing two capacitors used in the LCD circuit to better match the voltage rating of the LCD module and provide increased reliability.

Detailed Description of Change:

Change C1 & C4 from 2.2uF, 10V to 2.2uF, 25V. Since the new caps are the same physical size no footprint or PCB changes are required and this change has no impact on existing units.

Products Affected:

Effected Product (Rev 5.0 - 7.2)	Recommended Replacement Product (Rev 7.3)
uEZGUI-1788-43WQR	uEZGUI-1788-43WQR
uEZGUI-1788-43WQR-BA	uEZGUI-1788-43WQR-BA
uEZGUI-1788-43WQR-BA-NT	uEZGUI-1788-43WQR-BA-NT

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers' orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

05/12/15 PCN Date, the date this document was released for distribution to customers and distributors.

05/01/15 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.

Reference Documents: <http://www.teamfdi.com/wiki/doku.php?id=namespace:uezgui-1788-43wqr#uezgui-1788-43wqr>

1. uEZGUI-1788-43WQR Brochure.pdf
2. uEZGUI-1788-43WQR Quick Start Guide.pdf
3. uEZGUI-1788-43WQR Users Manual.pdf
4. uEZGUI-1788-43WQR_SCH_7p3.pdf
5. uEZGUI-1788-43WQR Rev 7.3 ECO



FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.