

<b>FDI</b>	<b>ENGINEERING CHANGE ORDER</b>		<b>ECO NO: 14-016</b>
			<b>Page 1 of 1</b>
<b>TITLE</b>	<b>DWG NO.</b>	<b>CURRENT REV</b>	<b>NEW REV</b>
uEZGUI-4088-43WQN	uEZGUI-4088-43WQN	1.1	1.2

**BACKGROUND:**

- FDI Part Number updates to Rev 1.2 BOM

**DESCRIPTION OF CHANGE:**

1. Change U10 from Consigned FDI PN: U500616-C Macronix PN: MX25L12835FMI-10G to FDI PN: U500616. **\*Both FDI PN U500616-C and U500616 Macronix PN: MX25L12835FMI-10G Part Numbers are Approved to Use on uEZGUI-4088-43WQN-BA Production.**
2. Change U1 from Consigned FDI PN: U500613-C NXP PN: LPC4088FET208,551 to FDI PN: U500613. **\*Both FDI PN U500613-C and U500613 NXP PN: LPC4088FET208,551 Part Numbers are Approved to Use on uEZGUI-4088-43WQN-BA Production.**
3. Change U25 from FDI PN: U500581 TI SN74LVC1G126DCKR to FDI PN: U500573 TI SN74LVC1G126DCKR (Duplicate Part Number)
4. Added Packaging Material to Rev 1.2 BOM: BG00004, LB00001, LB00103, BX00008, BX00009, BX00012.
5. Updated Test Software to Version V2.01

Reason for change: 1. REV 1.2 BOM CHANGES, Test Software Updated to Version 2.01		<b>Disposition/Affectivity</b>	
		Use as is	
		Rework to ECO	X
		Scrap & Rebuild	
		Record Change Only	
Prepared by:	CM	Date:	07/23/14
Approved by:		Date:	
Approved by:		Date:	
Approved by:		Date:	