

FDI	ENGINEERING CHANGE ORDER		ECO NO: 13-006
			Page 1 of 1
TITLE	DWG NO.	CURRENT REV	NEW REV
uEZGUI4.3	uEZGUI4.3	6.1	6.2

BACKGROUND:

- Removing the ISP connector from production boards.

DESCRIPTION OF CHANGE:

1. Change J3 to a DNL.

Reason for change: 1. Part availability and addition of alternate TTL serial interface.		Disposition/Affectivity	
		Use as is	
		Rework to ECO	
		Scrap & Rebuild	
		Record Change Only	x
Prepared by:	CS	Date:	2/22/13
Approved by:		Date:	
Approved by:		Date:	
Approved by:		Date:	